

Примеры калибровочного сертификата



Prüfprotokoll

Calibration certificate / Fiche de calibration

Typ : Type / Type:	PAA-41X / 50mbar / 81955.50		
Seriennummer : Serial no. / No. de serie :	44125	Produkt Nummer : Product no. / No. de produit :	244110.0511
Messbereich : Measurement range / Etendue de mesure :	0.02 ... 0.2	bar abs	
Komp. Temp. Bereich : Comp. temp. range / Gamme de temp. comp. :	10 ... 50	°C	
Speisung : Supply / Alimentation :	13 ... 28	V	
Ausgangssignal : Output signal / Signal de sortie :	0 ... 10	V	
Anschluss : Connector / Connecteur :	Binder 723 5-p		
	1 :	GND	5 : RS 485B
	2 :	+OUT	
	3 :	+Vcc	
	4 :	RS 485A	

Bemerkung :

Remark / Remarque :


Abweichung Messbereich (digital)

Deviation measurement range / Deviation étendue de mesure



Abweichung analoges Ausgangssignal

Deviation analog output signal / Deviation signal de sortie



Linearitätsfehler: -0.006 0.003 %FS(Lnorm) @ 25 °C

Linearity error / Erreur de linéarité:

Totales Fehlerband : -0.017 ... 0.149 %FS -0.014 ... 0.133 %FS @ 10 ... 50 °C

Accuracy (TEB) / Erreur totale :

PrüferIn : DZo

Test person / Contrôlé par:

Datum : 20.11.2014

Date / Date :